


ratiotec GmbH & Co. KG
Max-Keith-Straße 66
45136 Essen
Tel.: +49 201 361 490
Fax: +49 201 361 49 26
Email: info@ratio-tec.de

KALIBRIERUNGSANLEITUNG Soldi Smart Pro | Plus | Pro USD

CALIBRATION GUIDE Soldi Smart Pro | Plus | Pro USD




KALIBRIERUNGSANLEITUNG Soldi Smart Serie Plus | Pro | Pro USD


Eine kurze Kalibrierung kann helfen, wenn das Gerät Probleme anzeigt mit echten Banknoten verschiedener Währungen. Wenn das Problem durch eine defekte Komponente verursacht wurde oder eine vollständige Kalibrierung erforderlich ist, kontaktieren Sie bitte unseren technischen Service.

Ihr **ratiotec** Team


1. Stecken Sie den Soldi Smart an die Stromversorgung mit Hilfe des Netzteils.
2. Schalten Sie das Gerät ein, in dem Sie die **AN/AUS**-Taste drücken und warten Sie, bis das Gerät bereit ist.
3. Nach dem das Gerät sich eingeschaltet hat, drücken Sie **4x** die **AN/AUS**-Taste, in der Displayoberfläche wird „**ADJUST**“ angezeigt.
4. Führen Sie vorsichtig das **pinke** Kalibrierungspapier in das Gerät ein. Das Gerät empfängt das **pinke** Kalibrierungspapier und bringt es erneut zurück an die Gerätefront.
5. Daraufhin blinkt „**ADJUST**“ im Display. Führen Sie das **pinke** Kalibrierungspapier mehrmals in das Gerät ein, bis im Display „**OK**“ angezeigt wird (ca. **6 – 10 x**).
6. Sie können das Gerät jetzt ausschalten, es neu starten und testen.



Soldi Smart Plus



Soldi Smart Pro




Soldi Smart Pro (USD)

CALIBRATION GUIDE Soldi Smart Serie Plus | Pro | Pro USD


A quick calibration can help when the device shows problems recognising real banknotes of different denominations. If the problem is caused by a defective component, or in case a full calibration is required, you will need to contact the technical support.

Your **ratiotec** Team.


1. Plug the Soldi Smart to the power supply by means of the adaptor.
2. Turn on the device normally by pressing the **ON/OFF** key. The device turns on automatically. Wait, until it is ready.
3. While the device turns on, press **4 times** the **ON/OFF** key. The display will show the message „**ADJUST**“.
4. Introduce the **pink** calibration paper as if it was a banknote. The device will take it and return it each time through the front.
5. On the display, „**ADJUST**“ will blink. Afterwards, feed the **pink** calibration paper several times (**6 – 10 times**), until the message „**OK**“ appears on the screen.
6. Unplug the device to turn it off. Switch on the device again normally and test.



Soldi Smart Plus



Soldi Smart Pro



Soldi Smart Pro (USD)